

## PowerBook Fax/Data Modem: There Is No Rev. 1.2 of ROM (7/93)

On the Fax Sender 1.0.3 disk there is a Read Me document that refers to PowerBook Fax/Data Modem firmware version 1.2.

I have a customer who has version 1.0 of the firmware. He would like to know the difference between version 1.0 and 1.2 of the firmware and how he goes abut getting the updated ROM version.

DISCUSSION -----

Although at one time there were plans to make a version 1.2 of the Fax/Data Modem ROM, it was never produced. Unfortunately, the Read Me file was included as part of the Fax Sender 1.0.3 software by mistake. Since the 1.2 ROM does not exist, there is nothing to upgrade.

Support Information Services

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:12637