



# Tech Info Library

## Performa: SCSI Problems With Third-Party Drives (7/93)

Revised: 7/22/93  
Security: Everyone

Performa: SCSI Problems With Third-Party Drives (7/93)

=====  
Article Created: 21 July 1993

TOPIC -----

I have a Syquest drive that works fine on my IIsi. When I attach it to the SCSI port of my Performa 450 I can't boot to the desktop. What can I do?

DISCUSSION -----

There have been some odd SCSI situations with some third-party drives on all types of Macintosh computers. If the drive works on your Macintosh IIsi, then it probably isn't a drive problem, but you should still check it.

First, make sure that the SCSI ID is not set to either 0 or 7.  
Next, try removing the termination of the drive. In some cases, this will fix the problem.

If you still can't boot, try double termination. In other words, try adding another terminator to the drive.

Copyright 1993, Apple Computer, Inc

Tech Info Library Article Number:12669