

Quadra 950: Blank Screen with SuperMac Thunder II Light (8/93)

Revised: Security:	
-	ank Screen with SuperMac Thunder II Light (8/93)
Quadra 990. Die	ink Screen with Supermat mander if fight (0793)
	l: 2 August 1993
TOPIC	
When I power up my system, my monitor is blank.	
DISCUSSION	

There are several things to check with SuperMac Thunder II Light when your screen is blank or displays garbage:

- Your monitor may be connected to the internal board (on-board connector), and not to the SuperMac board installed in one of the NuBus slots.
- Also, remove the cover and ensure that the SuperMac video card is properly seated in the NuBus slot.
- Hold down the option key and restart your Quadra 950. This will trigger SuperMac's system for cycling through all monitor sizes supported. When the image of the keyboard on the screen is clear and/or the name of your monitor appears on the screen, press the space bar. Your Macintosh will restart with the right screen settings.

To locate a vendor's address and phone numbers, use the vendor name as a search string.

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:12835