



Tech Info Library

Run Disk First Aid 7.1.1 or Later Before HD SC Setup (12/93)

Revised: 12/13/93
Security: Everyone

Run Disk First Aid 7.1.1 or Later Before HD SC Setup (12/93)

=====
Article Created: 4 August 1993
Article Reviewed/Updated: 10 December 1993

TOPIC -----

I received the message "Unable to unmount drive, file may be in use."
This happened when I tried to update the hard disk drivers with the
new Apple HD SC Setup from the Hardware System Update 2.0 as explained
in the ReadMe file. When I rebooted the Macintosh, the hard drive
wouldn't mount, and it displayed a flashing question mark.

DISCUSSION -----

Most likely, the system had already run into the problem resolved in
the updated drivers. You must run Disk First Aid 7.1.1 or later to
ensure that the problem isn't present on the disk prior to updating
the drivers with HD SC Setup 7.2. If this order isn't followed, then
updating the drivers will fail.

HD SC Setup version 7.2.2 fixes this problem.

Article Change History:
10 December 1993 - Added information about HD SC Setup version 7.2.2.
23 August 1993 - Revised to include Disk First Aid versions later than
7.1.1.

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:12862