



# Tech Info Library

## PowerBook External Monitor Freeze-up & Connectix Utills (8/93)

Revised: 7/8/94  
Security: Everyone

PowerBook External Monitor Freeze-up & Connectix Utills (8/93)

=====  
Article Created: 12 August 1993

TOPIC -----

I have Connectix PowerBook Utilities (CPU) version 1.0 installed on my PowerBook with external monitor port.

When the PowerBook 160 or 180 (or other models with the video out feature) display dims after the set amount of time, and if a second monitor is attached, the display will not refresh when a key is depressed. Both the internal display and the external monitor light up but remain blank, except for the cursor. The only way to recover is to restart the computer.

DISCUSSION -----

This version of CPU is not compatible with the video out feature of the new PowerBooks. Connectix does have a compatible version of the utility, 1.0j.

Version 2.0 of Connectix PowerBook Utilities also is available, with enhanced features as well as compatibility with all PowerBooks to date.

Call Connectix for the latest information and to obtain the current release of the software. To locate a vendor's address and phone numbers, use the vendor name as a search string.

Support Information Services

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:12950