

## Tech Info Library

## Power Macintosh: New Monitor Port Uses HDI-45 Socket (7/95)

Revised: 7/11/95 Security: Everyone

Power Macintosh: New Monitor Port Uses HDI-45 Socket (7/95)

\_\_\_\_\_\_

Article Created: 24 February 1994 Article Reviewed/Updated: 10 July 1995

TOPIC -----

This article describes:

- HDI-45 socket on all Power Macintosh computers
- Monitors supported through the HDI-45 socket
- DRAM supported video when using this port
- Adapter cable needed for monitors with a DB-15 plug.

DISCUSSION -----

AllPower Macintosh 6100, 7100, 8100 computers have an HDI-45 monitor socket located on the back panel. The Power Macintosh 7100, 8100, and all designated AV models also provide a DB-15 monitor socket. In addition to the Apple AudioVision 14 monitor, the HDI-45 interface supports these other monitors when used with the HDI-45 Adaptor cable:

Monitor	Size (pixels)	Color depth (bits)
12-inch RGB	512 by 384	16
14-inch RGB	640 by 480	16
15-inch portrait	640 by 870	8
15-inch Multi-Scan	640 by 480	16
15-inch Multi-Scan	832 by 624	8
16-inch RGB	832 by 624	8
17-inch Multi-Scan	640 by 480	16
17-inch Multi-Scan	832 by 624	8
20-inch Multi-Scan	640 by 480	16
20-inch Multi-Scan	832 by 624	8
16-inch RGB	832 by 624	8

VGA 640 by 480 8

Note:

Built-in video (HDI-45 with 640K DRAM support) doesn't support any monitor with a resolution greater than 832 by 624. To use a larger monitor (19-inch, 20-inch, or 21-inch) at these higher resolutions, a third-party video card or the AV card must be used.

When using the HDI-45 connector, frame buffering for monitor support is provided through a 640K DRAM space. There is no dedicated VRAM when using this port.

A video adapter cable (Part #M2681LL/A) is needed to connect a monitor with a DB-15 connector to a HDI-45 built-in port. This cable comes standard with every Power Macintosh 6100, and is offered as an option for the Power Macintosh 6100AV. With the Power Macintosh 7100, 8100, or AV models, the adapter cable is offered as an option to connect an additional display (other than the Apple AudioVision 14) to your computer.

Article Change History:

10 Jul 1995 - Added information on Multiple Scan Displays.
09 Jan 1995 - Excluded speed from Power Macintosh model numbers.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Tech Info Library Article Number:14732