



Tech Info Library

Power Macintosh: AV Upgrade and Composite Video Ports (3/94)

Revised: 3/11/94
Security: Everyone

Power Macintosh: AV Upgrade and Composite Video Ports (3/94)

=====
Article Created: 10 March 1994

TOPIC -----

This article describes the missing composite video ports when upgrading a Macintosh Quadra 840AV or 660AV to a Power Macintosh.

DISCUSSION -----

When a Macintosh Quadra 840AV or 660AV is upgraded to a Power Macintosh AV, the composite video ports will be missing.

These ports are provided via a composite video adapter which is connected to the S-video ports of the AV card.

Support Information Services

Copyright 1994, Apple Computer, Inc.

Tech Info Library Article Number:14861