

Power Macintosh: Sampled Sound Playback Issue (3/94)

Revised:	3/11/94
Security:	Everyone
Power Macintosh	n: Sampled Sound Playback Issue (3/94)
=========	.======================================
Article Created: 10 March 1994	
TOPIC	
This article de	escribes sampling rate playback change.
DISCUSSION	

The sampling rate of $22.05~\mathrm{kHz}$ replaced the sampling rate of $22.254~\mathrm{kHz}$ in older Macintosh models. This new rate was changed for compatibility with the $44.1~\mathrm{kHz}$ audio CD sampling rate.

For sound samples made at the $22.254~\mathrm{kHz}$ rate, playback at the $22.05~\mathrm{kHz}$ results in a 1% change in pitch (lower).

Support Information Services

Copyright 1994, Apple Computer, Inc.

Tech Info Library Article Number: 14867