



Tech Info Library

Personal LaserWriter LS: Needs Updated Driver for AV's (10/95)

Revised: 10/30/95
Security: Everyone

Personal LaserWriter LS: Needs Updated Driver for AV's (10/95)

=====
Article Created: 24 March 1994
Article Reviewed/Updated: 30 October 1995

TOPIC -----

My Personal LaserWriter LS won't print properly when connected to any AV Macintosh Computer. It prints one page then gives a time out error and tells me to check the serial cable. How can I fix this?

DISCUSSION -----

Use the newer version of the driver for the Personal LaserWriter LS named 'LaserWriter 300' v1.2. Using this driver allows printing from the AV Series Macintosh computers. This software originally shipped with the AV Macintosh computers and is included in System 7.5.x.

Article Change History:
30 Oct 1995 - Updated driver availability in System 7.5.

Support Information Services

Copyright 1994-95, Apple Computer, Inc

Tech Info Library Article Number:14992