



# Tech Info Library

## DOS Compatibility Card: PC Exchange needs 32-bit addressing 5/94

Revised: 5/24/95  
Security: Everyone

DOS Compatibility Card: PC Exchange needs 32-bit addressing 5/94

=====

Article Created: 5 May 1994

TOPIC -----

I have a Quadra 610 DOS Compatible computer with PC Exchange 2.0DC. When I try to initialize a disk, the computer freezes on me and I have to restart my computer. Sometimes it allows me to initialize the disk, but when I click the window close box, the computer freezes on me. If I remove PC Exchange, this problem goes away. Why?

DISCUSSION -----

PC Exchange 2.0DC needs 32-bit addressing turned on. If you turn on 32-bit addressing in the Memory control panel, you won't experience this problem.

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:15296