



Tech Info Library

PowerBook 160/180: Problems Using an External Monitor (1/96)

Revised: 1/15/96
Security: Everyone

PowerBook 160/180: Problems Using an External Monitor (1/96)

=====
Article Created: 9 June 1994
Article Reviewed/Updated: 15 January 1996

TOPIC -----

I have problems when my startup screen and menu bar are located on an external monitor connected to my PowerBook 160 or 180 computer with System 7.1. When I try to shutdown, the computer will display either a "Finder - Illegal F-line instruction" or "Finder - error type 41" error. The System Updates (2.0.1 and 3.0) do not seem to help this problem. Can you help?

DISCUSSION -----

You will get this error on a PowerBook 160 or 180 with System 7.1.x when you connect an external monitor, multiple ADB devices, and both the menu bar and the startup screen are moved to the external monitor.

The problem will only occur if:

- 1) multiple ADB devices (the Apple Adjustable Keyboard acts like multiple devices) are attached
- AND-
- 2) both the menu bar and the startup screen are placed on the external monitor.

The problem does not occur with the PowerBook 165c or PowerBook 180c. It also does not occur with the PowerBook 500 Series computers.

Two temporary workarounds are to either:

- not use multiple ADB devices
- or-
- not put both the menu bar and the startup screen on the external monitor.

The permanent fix is to update to System 7.5.x.

Article Change History:

15 Jan 1996 - Added system 7.5.x fix information.

Support Information Services

Copyright 1994-96, Apple Computer, Inc.

Tech Info Library Article Number:15576