



# Tech Info Library

## Power Macintosh: 8•24 GC Video Needs New Monitors CDEV (6/94)

Revised: 6/29/94  
Security: Everyone

Power Macintosh: 8•24 GC Video Needs New Monitors CDEV (6/94)

=====  
Article Created: 21 June 1994  
Article Reviewed/Updated: 29 June 1994

### TOPIC -----

I have a Power Macintosh 8100/80 with an 8•24 GC card connected to an Apple Two-Page Mono Monitor, and internal video card connected to an Apple 16-in Color monitor. When I restart the monitor, the Two-Page Monitor defaults to black and white. Resetting PRAM and doing a clean installation of system software has not corrected the problem.

### DISCUSSION -----

The problem is caused by the version of the Monitors Control Panel. Installing v7.3.2 of the Monitors Control Panel corrects this problem. You can find the correct version of the Monitors Control Panel on the Apple Multiple Scan Display Software Disk.

You do not need to go through the entire installation process to correct this problem. Simply drag the Monitors Control Panel from the Apple Multiple Scan Display Software Disk to your System folder.

Article Change History:  
29 June 1994 - Clarified the discussion section.

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:15658