

630 Family Computers: Not Compatible With Apple IIe Card (7/94)

No. The 630 Family computers operate only in 32-bit addressing mode, so they do not support the Apple IIe card for the Macintosh LC.

Copyright 1994, Apple Computer, Inc.

Tech Info Library Article Number: 15824