



# Tech Info Library

## LaserWriter Pro 630: Requires LaserWriter 7.2 or Greater (10/94)

Revised: 10/27/94  
Security: Everyone

LaserWriter Pro 630: Requires LaserWriter 7.2 or Greater (10/94)

=====  
Article Created: October 26, 1994

TOPIC -----

I am using LaserWriter driver version 7.1.2 that came with System Software 7.1 to print to a LaserWriter Pro 630. When I select 'Print Window' or 'Print Desktop' nothing ever prints. The lights on the printer continue to blink until the printer is turned off and on again.

DISCUSSION -----

The printer is experiencing a processing error. When printing to the LaserWriter Pro 630 on an Ethertalk network, the Macintosh should have version 8 of the LaserWriter driver, or version 7.2 supplied with the printer. Processing errors like this are common when using LaserWriter driver 7.1.2.

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:16613