

Power Macintosh 8100/110: Must Use System 7.5 (11/94)

	vised: curity:	11/14/94 Everyone
Power Macintosh 8100/110: Must Use System 7.5 (11/94)		
Article Created: 03 November 1994 Article Reviewed/Updated: 14 November 1994		
TOE	PIC	
	it possible ver Macintosł	to run System 7.1.2 (the Power Macintosh version) on the new n 8100/110?
DIS	SCUSSION	
		Macintosh 8100/110 requires System 7.5. Below is some information e side effects of running older system software on the 8100/110.
	Enabler), wh with the old	PPC Enabler is named the same as the old Enabler (PowerPC nat happens if you install it in the 7.1.2 system folder along d enabler? t a System Error.
	What are the symptoms/results if you try to boot a Power Macintosh 8100/110 with System 7.1.2? You will get an error message that says that the System Software is too old to run on this machine.	
	8100/110 wit You will get	e symptoms/results if you try to boot a Power Macintosh th the original System 7.5? an error message that says that the System Software is too on this machine.
	run?	PPC enabler is installed in an original Power Macintosh, will it
A.		because the enabler will not be used. It will use the generic code to run the system.
	It will stil	ne revised version of System 7.5 be named? I be called System 7.5. Since this is a superset of the 5, it won't be necessary to revise the version number.

..TIL16672-Power_Macintosh_8100-110-Must_Use_System_7-5_11-94.pdf

- Q. What items have been changed in System 7.5 for support of the Power Macintosh 8100/110?
- A. FinderPowerPC Finder UpdatePowerPC EnablerHD SC Setup
- Q. Is this version backwards compatible with all computers that use System 7.5?
- A. Yes, EXCEPT you cannot boot older Power Macintosh computers with the Power Macintosh 8100/110 Disk Tools disk. It requires the System 7.5 Disk Tools disk. On older machines, you get a "this machine needs newer software to boot..." message, which is the correct behavior.

Article Change History: 14 Nov 1994 - Revised wording in Discussion.

Support Information Services

Copyright 1994, Apple Computer, Inc.

Tech Info Library Article Number:16672