

Power Macintosh: Disk Copy Gives Error Copying (12/94)

Revised: 12/22/94 Security: Everyone

Power Macintosh: Disk Copy Gives Error Copying (12/94)

Article Created: 22 December 1994

TOPIC -----

I have a Power Macintosh computer and I am trying to use Disk Copy to make disks. However, when I try to copy over preformatted MS-DOS formatted disks, I get an error message. If I put the disk into the Macintosh after quitting Disk Copy, it looks like it copied the disk properly, but the disk doesn't work. What is going on?

DISCUSSION -----

There are two issues at work here. The Power Macintosh floppy driver and the Disk Copy application.

When using a 720K MS-DOS formatted disk with an 800K Macintosh image file, Disk Copy (or any other disk image utility such as DART or Disk Dup) runs out of useable tracks at the end of the disk. On non-Power Macintosh computers, Disk Copy is able to "add" the extra tracks needed. On Power Macintosh computers, because of some timing issues in the Power Macintosh floppy driver, Disk Copy is not able to "add" the extra tracks, so you get the error message at the end. These timing issues are known to Engineering, but since Disk Copy was written before the advent of the Power Macintosh computers, it is not able to account for the timing differences. Disk Copy needs to be revised to account for the timing differences in the Power Macintosh floppy driver. Since there is not a group tasked with revising Disk Copy, this may or may not be done soon.

Workarounds

There are two workarounds for this problem:

- 1) Use the Erase Disk option in the Special menu, and format the disk as a Macintosh disk.
- 2) Use a bulk-eraser to remove all track and sector information.

..TIL16927-Power_Macintosh-Disk_Copy_Gives_Error_Copying_12-94.pdf

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:16927