



Tech Info Library

Power Macintosh 8100/110: No Official AV Card Support (7/95)

Revised: 7/11/95
Security: Everyone

Power Macintosh 8100/110: No Official AV Card Support (7/95)

=====
Article Created: 15 February 1995
Article Reviewed/Updated: 11 July 1995

TOPIC -----

I notice that the Power Macintosh 8100/110 does not ship with an AV video card. Will the Power Macintosh AV video card work in a Power Macintosh 8100/110?

DISCUSSION -----

While designed to function in any Processor Direct Slot (PDS) equipped Power Macintosh computer, the Power Macintosh AV Card was never thoroughly tested in the Power Macintosh 8100/110. Therefore, Apple does not support the use of the AV card in the Power Macintosh 8100/110.

Due to the similarity of the design of the Power Macintosh 8100/80, 8100/100, and 8100/110, it is unlikely you will experience a problem when installing the AV card into a Power Macintosh 8100/110.

However, because this configuration was not thoroughly tested by Apple, we cannot officially support this configuration if a problem arises.

Article Change History:
11 Jul 1995 - Reviewed for technical accuracy.
17 Mar 1995 - Revised compatibility statement of AV card in a Power Macintosh.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:17197