



# Tech Info Library

## LaserWriter Pro 810: 802.2 Novell Ethernet Frame Types (2/95)

Revised: 2/16/95  
Security: Everyone

LaserWriter Pro 810: 802.2 Novell Ethernet Frame Types (2/95)

=====

Article Created: 16 February 1995

TOPIC -----

Does the LaserWriter Pro 810 support 802.2 Novell Ethernet frame types?

DISCUSSION -----

The LaserWriter Pro 810 does not support 802.2 frame types, only 802.3 and Ethernet\_II. For this printer to function in a Novell NetWare environment (and 802.2 is the default with Netware 3.12 and 4.x), the NetWare autoexec.ncf file must have an entry for one of these other protocols to support a LaserWriter Pro 810 printer.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:17204