

Plaintalk 1.4.1: Can't Install Recognition on 8-bit Mac (9/95)

Revised: 9/1/95 Security: Everyone Plaintalk 1.4.1: Can't Install Recognition on 8-bit Mac (9/95) _____ Article Created: 23 August 1995 Article Review/Updated: 1 September 1995 TOPIC ------When I try to install English Speech Recognition (ESR) on my Performa 5200 or Performa 6200 series computer, I get an error message stating that "English Speech Recognition requires 16-bit sound input. It cannot be used on this Macintosh." DISCUSSION ------First, make sure that your computer supports 16-bit sound input: Step 1 _ _ _ _ _ _ Choose Control Panels from your Apple menu. Step 2 ____ Open the Sound control panel. Step 3 ____ Choose "Sound Out" from the "Alert Sounds" pull down menu. If the 16-bit sound input radio button is grayed out, you only have 8-bit input, and English Speech Recognition will not work. If 16-bit is not grayed out, make sure there is a dot in the radio button next to it. Step 4 ____ Use the close box in the upper left corner to close the Sound control panel.

..TIL18463-Plaintalk_1-4-1-Cant_Install_Recognition_on_8-bit_Mac_9-95_(TA34319).pdf

Now you can follow these steps to override the error message and install the ESR software: Step 1 ____ Restart your Macintosh computer, hold down the shift key on the keyboard until you get the message "Welcome to Macintosh, Extensions Off" screen. Step 2 ____ Open the ESR 1.4.1 installer either from the floppy disk or the folder you downloaded, ignore the error message you saw before. Step 3 ____ Select "Custom Install" from the "Easy Install" pull down menu. Make sure the check-box next to "English Speech Recognition Software" has an X in it, then click on the Install button in the bottom right hand side of the window. Step 4 ____ Restart your Macintosh computer. Plaintalk is ready to use. Step 5 ____ Under the Apple Menu, choose Control Panels. Click on the button with the question mark on the yellow background to go through an Introduction to Speech Recognition. Article Change History: 01 Sep 1995 - Modified to include Performa 5200 series. Support Information Services Copyright 1995, Apple Computer, Inc. Tech Info Library Article Number:18463