



Tech Info Library

PlainTalk 1.4.1: No Sound Speakable Items Enabled (11/96)

Revised: 11/11/96
Security: Everyone

PlainTalk 1.4.1: No Sound Speakable Items Enabled (11/96)

=====
Article Created: 23 October 1995
Article Reviewed/Updated: 11 November 1996

TOPIC -----

I just installed PlainTalk 1.4.1 on my Macintosh Performa 6200. When I turn on Speakable Items in the Speech Control Panel, I no longer hear any sound from my computer. The speech recognition is working and executing the commands I speak, but there are no feedback sounds or system beeps playing from my speaker. It is as if my speakers are muted. I checked the Sound control panel, and it is set at full output volume to the internal speaker of the computer.

DISCUSSION -----

This issue has been resolved in PlainTalk 1.5, which is available from <http://www.speech.apple.com>. The following computers require PlainTalk 1.5 in order to properly use speech recognition:

- Macintosh 5200CD family: Macintosh 5200/75 LC, Performa 5200, Performa 5210, Performa 5215, and Performa 5220.
- Macintosh 5300CD family: Macintosh 5300/100 LC, Performa 5300.
- Macintosh 6200CD family: Performa 6200, Performa 6214, Performa 6216, Performa 6218, Performa 6220, and Performa 6230.
- Macintosh 6300CD family: Performa 6300, Performa 6290

Article Change History:
11 Nov 1996 - Added 1.5 information.
24 Jul 1996 - Updated information based on info in Read Me.
13 Jul 1996 - Updated information.

Copyright 1995-96, Apple Computer, Inc.

Tech Info Library Article Number:18802