



Tech Info Library

Performa 6320: SoundLib In Extensions Folder Not Needed (1/97)

Revised: 1/17/97
Security: Everyone

Performa 6320: SoundLib In Extensions Folder Not Needed (1/97)

=====
Article Created: 13 January 1997

TOPIC -----

I have a Macintosh Performa 6320 computer. After using my computer for a few weeks, the sound no longer worked. My menu bar flashed, but I did not hear any sound. I checked my Extensions folder and I noticed a file called "SoundLib". After removing this file from my System Folder and restarting, I was able to restore sound on my computer. Do I need this in my System Folder or can I delete it permanently?

DISCUSSION -----

Owners of Macintosh Performa 6320 computers should delete this SoundLib file from the Extensions folder. However, any time you "Restore System Software" or "Restore all Software" from the Performa CD, it will be reinstalled, so you need to remove this file again.

The SoundLib file is used only for development and is not needed by any of the third party or Apple Computer software applications included with your Macintosh Performa computer. This SoundLib file is harmless and will not cause any data loss or crashes.

Copyright 1997, Apple Computer, Inc.

Tech Info Library Article Number:20806