# ..TIL58527-iMac\_(Slot\_Loading)\_Buzzing\_Noise\_After\_Shutdown.pdf

Apple Service - Troubleshoot and Repair

# **Tech Info Library**

Home - CD Index - Feedback

Apple Spec DB - Hard Drives Matrix - Memory Guide -

Parts DB - Service Manuals - Software Troubleshooting

Service Programs Manual Index - U.S. - Canada

CompTIA Codes - Ordering Parts FAQ - Product Service

Matrix - REAs - Service Excellence

# TITLE

iMac (Slot Loading): Buzzing Noise After Shutdown

Article ID: 58527 Created: 11/22/99 Modified: 1/24/00

#### **TOPIC**

This article describes a buzzing noise heard from the iMac (Slot Loading) after shut down.

## DISCUSSION

A very small number of iMac (Slot Loading) computers may produce a buzzing or humming noise from the speakers after shut down. The noise can last for several minutes and will go away if the power cord is unplugged from the computer.

If your iMac (Slot Loading) makes a loud buzzing or humming noise after shut down, contact Apple or an Apple-authorized service provider for assistance in getting the issue resolved.

## **EXTENDED Information** - Apple Internal Use - Service Providers and Support Professional

The root cause of the buzzing noise is on the main logic board. The problem is most likely to occur when the iMac (Slot Loading) is plugged into a 220 volt or higher power source, however, it can occur when the iMac is plugged into a 110 volt power source.

If a customer complains that their iMac (Slot Loading) makes a loud buzzing or humming noise after shut down, replace the main logic board under warranty. Refer to Service Source for instructions on replacing the main logic board.

# **Document Information**

Product Area: iMac (Slot Load)

Category: Sub Category:

APPLE NEED-TO-KNOW CONFIDENTIAL: Do NOT forward, copy, or otherwise replicate or disseminate verbally, electronically, or in hardcopy (except to those individuals within your organization who have a legitimate business need to know the information, and who have agreed in writing, to keep it confidential), unless Apple has given prior written authorization.

Copyright © 1999-2000, Apple Computer, Inc.