



Tech Info Library

Apple PCI Token Ring Card: Does Not Work With LLC 2 (5/96)

Revised: 5/24/96
Security: Everyone

Apple PCI Token Ring Card: Does Not Work With LLC 2 (5/96)

=====
Article Created: 24 May 1996

TOPIC -----

I cannot seem to get 802.2 Logical Link Control version 2 (LLC 2) support when using Apple's PCI Token Ring card. I am using Attachmate's IRMA for the Mainframe 4.0.5. Attachmate tells me that Apple's PCI Token Ring card does not support this protocol. I tried to use the MacMainframe software and the LLC 2 section is grayed out.

What is wrong? Does the Apple PCI Token Ring Card not support LLC 2?

DISCUSSION -----

No, Apple's PCI Token Ring card does NOT support LLC 2. Apple has no plans at this time to add support for LLC 2.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:19861